WAR DEPARTMENT HEADQUARTERS ARMY AIR FORCES WASHINGTON

Possibly this type and crew members. Prepared by S&R Air Cas Sub-Sec RMK/MGN/vsg*

MISSING AIR CREW REPORT

IMPORTANT: This report will be complied in triplicate by each Army Air Forces organization within 48 hours of the time an aircraft is officially reported missing.

1.	ORGANIZATION: LocationC	ommand or Air Force	
	GROUP SQUADRON 2 Emerg Re	Sodi DETACHMENT	
2,	SPECIFY: Point of Departure	: Course 190	
•	SPECIFY: Point of Departure Intended Destination WEATHER CONDITIONS AND VISIBILITY AT TIME	_: Type of Mission	
3.	WEATHER CONDITIONS AND VISIBILITY AT TIME	OF CRASH OR WHEN LAST REPORTED:	
4.	GIVE: (a) Date 10 Oct 45 Time 1755	: and location of last known	
	whereabouts of missing aircraft Mt.	Media as 1500 yrds off the coast	f#
	(b) Specify whether () Last sighted	: () Last contacted by radio:	
	() Forced down: () Seen to crash:	or () Information not available.	
50	AIRCRAFT WAS LOST, OR IS BELIEVED TO HAVE	BEEN LOST, AS A RESULT OF (Check	
	only one: () Enemy Aircraft: () Enemy An	ti-Aircraft: () Other circums-	
,	tances as follows Crashed into see while 1	anding on return from west coast	of
6.	AIRCRAFT: Type, model and Series 04-10-4	: AAF Serial No. 44-34052	Panay
10	ENGINES: Type, model and Series (c)	: AAF Serial No. (a)	
0	TARGETTED HIPADONG (Burned of holos Males The	(d)	
0.	INSTALLED WEAPONS (Furnish below Make, Typ	e and Serial Number)	
	(a) (b) (c) (e) (f) (g)		
9	THE PERSONS LISTED BELOW WERE REPORTED AS:	(a) Pattle Coquelty	
	THE TENDONO LICIED DELOW WENT REPORTED AS:	(b) Non-Battle Casualty	
10-	NUMBER OF PERSONS ABOARD AIRCRAFT: Crew	Passangers & Total	
	(Starting with pilot, furnish the followin	g perticulars: If more than 11	
	persons were aboard aircraft, list similar		
	and attach original to this form).	par oroazar o on popurato bisco	
	Name in Full	Serial	
	Crew Position (Last Name First)		
1.	Pilot Haves Frank B.		
2.	Co-Pilot Leonard John F.	The state of the s	
3.	Papales Wayne H	Per 368903/3 KTA	
40	Passenger Kell William	let It STA	
20	Cadiao, Silverio L.	Cept (P.A.) PTD	
0.	Miller, Leonard C.		
10	Hubbard, Robert N.	CONTRACTOR OF A SAME PRODUCT OF THE PROPERTY O	
9.	Garvey, John T.		
10.	McCary, Thomas J.	Pfc SIA	
11.			
17.	IDENTIFY BELOW THOSE PERSONS WHO ARE BELIE	VED TO HAVE LAST KNOWLEDGE OF	
	AIRGRAFT, AND CHECK APPROPRIATE COLUMN TO	INDICATE BASIS FOR SAME:	
	A A STREET STREET, STREET STREET, STRE	Check Only One Column	
	Name in Full Serial Conta	cted Last Saw Saw Forces	
	Name in Full Serial Conta (Last Name First) Rank Number By Rank	dio Sighted Crash Landing	
1.			
2.			
3.			
12.	IF PERSONNEL ARE BELIEVED TO HAVE SURVIVED	, ANSWER YES TO ONE OF THE	
	FOLLOWING STATEMENTS: (a) Parachutes were used: (b) Persons were		
	seen walking away from scene of crash : or (c) Any other reason		
12	(Specify)		
-2.	. ATTACH SERIAL PHOTOGRAPH, MAP, CHART, OR SKETCH, SHOWING APPROXIMATE		
1	LOCATION WHERE AIRCRAFT WAS LAST SEEN.		
-40	ATTACH EYEWITNESS DESCRIPTION OF CRASH, FORCED LANDING, OR OTHER CIRCUMSTANCE PERTAINING TO MISSING AIRCRAFT.		
5	. ATTACH A DESCRIPTION OF THE EXTENT OF SEARCH IF ANY, AND GIVEN NAME, RANK		
->-	SERIAL NUMBER OF OFFICER IN CHARGE HERE	on if ANI, AND GIVEN NAME, KANK	
	TOWNER OF OFFICER TH OUTUGE UPIE		
	Do	te of Report	
	See reverse side	te of Report	
	See reverse side	te of Report	

(Signature of Preparing Officer)

STATEMENT

During the period 5 Oct to 17 Oct 45 undersigned then Capt. P.A. was assigned to party whose mission to investigate a plane which was reported to have crashed on Mt. Madias, Culasi, Antique.

The aircraft upon completion of the mission was DA-10-A #44-34052 of which he was a passenger crashed while taking off on 10 Oct 45. Killed three U. S. American personnel namely pilot 2nd Lt. Frank P. Hayes, co-pilot 2nd Lt. John Leonard, and Wayne H. Peoples, and seriously injuring four others namely Sgt. Thomas J. McCary, S/Sgt. John T. Garvey and 1st Lt. William Kell.

The crash was approximately 1755 hours 10 Oct 45 with a distance of approximately 1500 yards off Culasi, Antique shore, heading 1900.

Injured Americans were evacuated to Mindoro by a P.T. Boat.

That the three who were killed went down with the plane and their bodies unrecovered.

That according to reliable information taken from fisherman in the vicinity the said plane is still in the same place where it crashed approximately 30 yards deep.

This is issued upon request of a representative AGRS at Iloilo City, Iloilo.

s/t/ SILVERIO L. CADIAO